

PAST PERFORMANCE/EXPERIENCE REFERENCE

Note: The bidder/offeror shall complete this form and submit as part of their bid/proposal. Complete one form for each reference. - make additional copies as necessary.

1. BIDDER/OFFEROR (COMPANY NAME) ORTIZ GROUP ENGINEERING & CONSTRUCTION SERVICES CORPORATION			
2. PROJECT STATUS AND TYPE <input checked="" type="checkbox"/> CURRENT <input checked="" type="checkbox"/> GOVERNMENT <input type="checkbox"/> PREVIOUS <input type="checkbox"/> NON-GOVERNMENT		3. PROJECT NAME AND LOCATION (CITY, STATE) IMPROVEMENTS TO RCA BLDG. AT CARR #2 KM 59, BARCELONETA, PR	
3. CONTACT PERSON/PROJECT MANAGER ENG. DAVID TORRES		5. CONTACT PHONE NUMBER 787-846-3400 / 787-314-4265	
6. Contract Number (if Federal Contract) 2007-000424		7. Value of Contract \$6,341,648.00	
8. TYPE OF FACILITY (office, hospital, manufacturing, school, etc.) UNIVERSITY ANA G. MENDEZ BUILDING		9. SIZE OF PROJECT (SQUARE FOOTAGE) 42,000 SF	
10. START DATE 1/07		11. END DATE 7/31/08	
12. FOR COMPLETED PROJECT-COMPLETED ON TIME? <input type="checkbox"/> YES <input type="checkbox"/> NO (IF NO, explain on back)		13. FOR CURRENT PROJECT -ON SCHEDULE? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (IF NO, explain on back)	
14. DESCRIPTION OF PROJECT AND COMPLEXITY PROJECT CONSIST OF SELECTIVE DEMOLITION WORKS OF EXISTING BUILDING, REINFORCED CONCRETE WORKS, CONSTRUCTION OF A NEW STEEL STRUCTURE, ROOF IMPEMEABILIZATION WORKS, INTERIOR FINISHINS AND ELECTRICITY AND PLUMBING WORKS			
15. TRADES UTILIZED ON PROJECT (LIST ALL)			
145 BUILDING SUPPLY	INTERAMERICAN EQUIP.	PR CONCRETE	PRESTIGE FIRESTOPPIN
ACHA TRADING	INTERTRADE	SHERWIN WILLIAMS	PR WIRE
ALL INTERIORS	JOSE GARRIGA HIJO	STEEL SERVICES	MASTER CONCRETE
AMERICAN AGENCIES	JUNCO STEEL	TRANE PR	BORINQUEN ROOFING
ATLANTIC FIRE SPRINKLERS	JUVAL TRADING	CARIBBEAN ATLANTIC	ELEVATOR
CIB CORPORATION	LUIS FREIRE	ENVIRO TAB	EURO AMERICAN STEEL
FERGUSON	POWER POLES	RC INSULATION	POWERLINE ELECTRICAL
GENERAL ELECTRIC	RALTRISAN	C/A MECHANIC	PRG INDUSTRIES
		ENGINEER METAL FORMS	
16. PROBLEMS ENCOUNTERED AND CORRECTIVE ACTIONS TAKEN			
SOIL CONDITIONS WERE NOT SUITABLE, DUE TO THIS IMPROVEMENTS TO SOIL WHERE REQUIRED			
ALONSO & CARUS			